

11/15/21

*The Village of
Dolgeville*

To: Village Board of Trustees
From: David Jaquay, DPW Superintendent
Date: 11/10/2021
Re: October 2021 Monthly Report

Current Work:

- Weekly Green Waste Collection
Most People are following the Green Waste Collection Policy. We will continue to pick up Leaves and Green Waste until snow falls. We continue to put out trucks for use of larger loads of green waste per Request.
- Weekly Checks of Sewers and Water Leaks
- Mowing & Weed eating of Village Parks & Trails as needed- Should be one more round of mowing left.
- Changing Garbage's at Parks Weekly. (First snow fall we will pull garbage's until spring)
- Daily 811 Requests
- Checking Storm drains after Rain events
- Flags have been put up for Veterans Day

Water/Sewer

- Cleaned Water Treatment Plant Filter this Month
- Sewer Complaint: 43 North Main Street. Blockage/Non-Functional. Sewer bagged for several hours with no relief. Sent camera in and found a plug in the line. Advised Homeowner to bring in Plumber. Homeowner advised 11/9/21 that plumber removed plug. DPW will go back and camera to confirm.
- Water Leak (E. Faville) Complaint of potential water leak. Tested for leak and confirmed no leak
- Water Shut off list was completed to the best of our ability. Some are inoperable and some are covered. Elm Street residence received a new valve box and stem.

Streets

- Checked and removed any debris in streets after the Microburst. We are still finding debris from the Microburst.

Garage

- Micro-Burst took off Roof of Salt Bin and 35'-40' x 50' of the Main Roof. – Clean up Debris in yard as well as worked with neighbor on removal of downed trees in the back of the properties. – DPW reinstalled roof on Salt Bin. – Tarped the Main Roof, installed new Tin on roof to replace damaged parts of roof on new building. – Met with Contractors on Roof repairs.
- New Truck has arrived- Needs to be lettered and have yellow Lights installed and 1 radio installed.
- First Deliveries of Salt are here.

- Re-arranged Garage to fit all trucks in and out of Weather
- “09” Freightliner is complete with new Headlights and wiring has been corrected to allow turn signals to work. Gear Oil changed on Chain Drive for Salt. Salt Spinner was Sand Blasted, rust Controlled and Painted. The Spinner Shoot was reinstalled. New Plow light Modules installed. Wing had paint removed, rust controlled and repainted. Cutting edges on plow removed, area behind plow rust controlled and painted. Wings and head plows installed.
- Workplace Violence and Sexual Harassment Course was Completed this Month.
- “12” Freightliner now has new batteries. Wings and head plow installed. In the process of Rust controlling plow.
- Garage Alarm reset a couple times (After Microburst & after a Power outage)
- Leaf Picker- had a coolant leak- was found to be a crack in the thermostat housing. Parts are hard to find. Part had to be braised and reinstalled. Old Muffler backfired and caused damage to the muffler- Muffler replaced. New Spring installed on throttle Governor to combat a runaway issue.
- Finished Cleaning the office. All filing is in order and office is now in a usable format.
- An Electric heater was placed in the breakroom. The gas-powered unit we have needs to be replaced.
- 8500- New Owner came and picked it up. Kodiak should be leaving on Friday. 350 can be put on auction after leaf season.

Parks

- Waiting for Rick Barnes to cut Trees in Plowe Park.

- Plowe Park- Work is progressing on the Main St Arch.
- Called and set a work order to have Meter Pulled on Center Park Pavilion. Check on as of Monday this week.
- Center Park Pavilion in the process of being dismantled.
- As of Tuesday, leaves were blown out of the parks for the first time.

To Do

- Need to check on the functionality of the camera system at Center Park as the park is starting to be vandalized again.
- Street Sign Replacement (Signs are faded and new Police Officers cannot read them). A discussion is requested with the Board Regarding quotes acquired.
- Cold Patching
- Update Water Books
- Service Plows
- Hydrant Markers to be put in place