

8-3

2/20/23

VILLAGE OF DOLGEVILLE
WASTEWATER TREATMENT FACILITY
97 VAN BUREN ST.
DOLGEVILLE, N.Y. 13329

ATTN: DOLGEVILLE VILLAGE BOARD 3 3
RE: MONTHLY REPORT JANUARY 12, 2022 to FEBRUARY 15, 2022

1. PERMIT COMPLIANCE FOR DECEMBER 2022

No permit violations to report.

2. MAINTENANCE

- Normal Preventive Maintenance
- Painting – Main hallway floor and cove base

3. GAS DETECTION/ALARMING (No update)

4. TRUNK SEWER LINING

KPI contacted us the day after the January Board meeting and performed prep for lining on 2/2/23. Roots were cut and heavy cleaning was completed on the pipe. Lining will be scheduled in the next several weeks, after MH 2A is uncovered. DPW has been assisting with locating MH 2A which is in the wooded area between the WWTP fence and Thresher Brook. It has not been located yet, but will need to be in order to line the pipe from Van Buren down to the treatment plant. KPI is scheduled to return on 2/24/23 with locating equipment.

5. NYSDEC INSPECTION

Dan Hayes and Talat Fathima of Region 6 NYSDEC conducted an inspection of the treatment plant on 1/19/23. A report was submitted to Mayor Puznowski and forwarded to the Board on 2/2/23. The plant was given an overall satisfactory status. As required, a laboratory sampling plan is being drafted for submission to DEC by 2/22/23.