

VILLAGE OF DOLGEVILLE  
WASTEWATER TREATMENT FACILITY  
97 VAN BUREN ST.  
DOLGEVILLE, N.Y. 13329

ATTN: DOLGEVILLE VILLAGE BOARD

RE: MONTHLY REPORT NOVEMBER 11, 2021 to DECEMBER 15, 2021

1. PERMIT COMPLIANCE FOR OCTOBER 2021

BOD and TSS concentrations for effluent were normal and within SPDES permit limits. However, removal efficiency for Total Suspended Solids (74%) was below the required 85% in October. Due to several 1"+ rainfall events in October, and resulting high flows due to excessive inflow/infiltration in the Village collection system, influent becomes less concentrated and treatment efficiency decreases. The flows exceed the design flow/capacity of the plant on days of heavy rain. Removal efficiency for BOD (86%) was acceptable.

2. MAINTENANCE

- Normal Preventive Maintenance
- 12/14/21 - Milton CAT generator service
- 12/15/21 – Solvents and Petroleum on-site to package hazardous waste for transport from facility. All accumulated waste/chemicals will be removed next week.
- 12/15/21 – Electrician on-site to assess exterior lighting
- 12/1/21 – DO Sensor in aeration tank error codes, ordered part
- 11/30/21 – Replaced thermostat in Influent Building

3. TRAINING

- 12/14/21 - Attended required HAZWOPER training provided by Comp. Alliance/Wright Insurance.
- Completed At Home Study Course for Grade IIA Water Operator, submitted course worksheets to New York Rural Water Association
- Attended webinar #4 in the series by NYSAWWA on the new lead and copper rule revision