

10-1
11/21/22

VILLAGE OF DOLGEVILLE
WASTEWATER TREATMENT FACILITY
97 VAN BUREN ST.
DOLGEVILLE, N.Y. 13329

ATTN: DOLGEVILLE VILLAGE BOARD
RE: MONTHLY REPORT OCTOBER 13, 2022 to NOVEMBER 17, 2022

1. PERMIT COMPLIANCE FOR SEPTEMBER 2022

No permit violations to report.

2. MAINTENANCE

- Normal Preventive Maintenance
- Preparation for winter months
- Aqualogics performed annual flow meter calibrations (10/25/22)
- Effluent chlorination/dichlorination ended (10/31/22)
- Replaced wear shoes on primary flights (11/8/22-11/10/22)

3. PRIMARY TANK CONCRETE REPAIRS AND STAIR REPLACEMENT PROJECT

National Building & Restoration Corp. completed new concrete stairs down to the pump station and replacement of the top of the wall of the primary tank (northeast wall). Work described in PCO 001 will continue. The last part of the project is to repair the face and top of the southwest wall of the primary tank. Change order 001 approved 11/16/22.

4. NYMIR Survey

It was recommended by NYMIR that combustible gas monitoring be installed in areas of the main building where digester gas piping exists. Potential leaks are a safety hazard. Gas monitoring and alarms would provide warning to anyone prior to entering those spaces. I have started the process of getting pricing on this equipment.